Annexure D

BUILDING SAFETY CERTIFICATE

1	1	1	
No. DB/03	2025-26	139	Dated: 09-05-2025

Certified that the existing building Montessori Prime School, (name of the building or premises) at Akt pamula, Akupamula(V). Munagala(m), Suryapet(dist) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block	Block	Block	Block	Block	Block
	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	G+2	-	-	-	8-6	

The building is owned/occupied by Montessori Prime School, Akupamula, Akupamula(V). Munagala(m), Suryapet(dist) (name of the Institution) have complied with the Building safety requirements occidance with National Building code Rules, and verified by the officers concerned of R&B department (Name of Department/ Govt.) on 8/5/20 15 of inspection) in the presence of Principal KJ Leema Rose (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 8 5 20 25 for a period of ______ years in accordance. (One year) with rule and subject to compliance of the specific conditions as appended.

- 1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
- 2. Should Procure Fire Safety Certificate from Fire Dept their recommendations should be followed and updated regularly.
- 3. Original Documents of the Building should be kept safety

Issued on 9/5/2025 at Suryapet by.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Executive Engineer

Name: T. SEETHA RAMAIAH

(R & B) District Office SURYAPET.

Designation: EXECUTIVE ENGINEER (R&B)

Name & Address of Department/ Office: District (REB) Spice